

639988

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL-U.S.OFFICIALS ONLY

COUNTRY	Poland	REPORT	
SUBJECT	New Ironwork Construction at Coast Artillery Barracks at Redlowo	DATE DISTR.	30 July 1954
DATE OF INFO.		NO. OF PAGES	3
PLACE ACQUIRED		REQUIREMENT NO.	RD
		REFERENCES	25X1

This is UNEVALUATED Information

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.  
THE APPRAISAL OF CONTENT IS TENTATIVE.  
(FOR KEY SEE REVERSE)

25X1

1. Ironwork construction was observed at the coast artillery barracks at Redlowo. It was not apparent when the barracks were observed in the autumn of 1953. The construction looks rather like an iron gate and protrudes about two meters above the trees which surround it.

## 2. Key to Sketch 1:

25X1

1. The Gdynia-Gdansk highway.
2. Ul. Redlowska; the surface is partly paved, but the part leading up to the barracks is earth; the whole length is planted on both sides with tall trees.
3. A road inside the barrack grounds, with a concrete surface.
4. A green painted gate with a protective barrier (szlaban).
5. Earth mounds, turf-covered, which partly conceal a wooden shed which stands behind them.
6. A large mound with a perpendicular wall on the south side. Wide, but not very high gates, which appear to be made of iron, were seen in this wall.
7. Concrete ventilator shafts.
8. A wooden shed, old, lacking one wall, on the north side.
9. A wooden ramp, about one meter high, which is linked with the entrance to the mound (No. 6).
10. Piles of rails and pipes with a diameter of from 6 to 10 cm.

SECRET/CONTROL-U.S.OFFICIALS ONLY

STATE	<input checked="" type="checkbox"/>	ARMY	<input checked="" type="checkbox"/>	NAVY	<input checked="" type="checkbox"/>	AIR	<input checked="" type="checkbox"/>	FBI	<input checked="" type="checkbox"/>	AEC							
-------	-------------------------------------	------	-------------------------------------	------	-------------------------------------	-----	-------------------------------------	-----	-------------------------------------	-----	--	--	--	--	--	--	--

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

SECRET/CONTROL-U.S.OFFICIALS ONLY

- 2 -

25X1

11. On top of a hill, a concrete bunker painted green.
12. An oblong earth mound, turf-covered. Near the mound are about 30 concrete steps.
13. On this mound (No. 12), a reflection of light could be seen, as though there were a window pane in this spot.
14. A brick single-story building, which looks like a store. The window panes are painted an ultra-marine color.
15. Wooden shed on an elevation.
16. A tall wooden gate. The fencing near this gate cannot be seen as it is hidden by the terrain.
17. Guardhouse.
18. Barracks which is not visible from the Gdynia-Gdansk highway.
19. Barracks on a slope.
20. A dwelling house.
21. A group of villas; nearby, small administrative buildings.
22. W/T station masts.
23. The ironwork construction, as mentioned at the beginning of this report. The position was determined with the aid of the W/T masts mentioned above (No. 22).
24. A sentry (observation) tower on top of a hill, of the type used by the W.O.P.
25. A small brick house; and nearby, a tall factory chimney.

3. Sketch 2.

General view of the ironwork construction from the vicinity of the coast artillery barracks.


25X1

SECRET/CONTROL-U.S.OFFICIALS ONLY

SECRET/CONTROL U.S. OFFICIALS ONLY

- 3 -

25X1



SECRET/CONTROL U.S. OFFICIALS ONLY